

Oil Field Environmental Incident Summary

Incident: 20160826181242 **Date/Time of Notice:** 08/26/2016 18:12

Responsible Party: DENBURY ONSHORE, LLC

Well Operator: DENBURY ONSHORE, LLC

Well Name: SFTU 12-25

Field Name: FRYBURG

Well File #: 13149

Date Incident: 8/26/2016 **Time Incident:** 12:30

Facility ID Number:

County: BILLINGS

Twp: 139

Rng: 101

Sec: 25

Qtr:

Location Description:

Submitted By: David Hill

Received By:

Contact Person: Brian Ehrmantraut
5320 LEGACY DR
PLANO, TX 75024-3127

General Land Use: Badlands Terrain

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	255	Barrels	220	Barrels	220	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/3/2016

Clean Up Concluded: 9/14/2016

Risk Evaluation:

None

Areal Extent:

Extent of off location impact is approximately 360' long by 5' to 20' wide.

Potential Environmental Impacts:

None

Action Taken or Planned:

A vacuum truck was dispatched to recover the standing fluid within the dikes. 220 bbls of produced water were recovered from within the dikes; approximately 15 bbls left the location, and 20 bbls remain in the saturated soils within the dikes. The affected soils within the dikes will be excavated and hauled to an approved landfill. The affected soils off location will be remediated as recommended by USFS.

Wastes Disposal Location:

Agencies Involved: USFS; BLM

Updates

Date: 8/29/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 8/29/2016, at 2:49 p.m. Work is being done at site to remove pieces from damaged storage tank. Spoke to personnel on site. Release was to the north off location and then proceeded to flow to the southwest. BioCal has been applied to area as requested by the U.S. Forest Service. I spoke with Forest Service personnel who said they will continue to oversee cleanup at this location.

Date: 8/29/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release of brine was not contained to the well pad. Further follow-up is needed.